



Report:
Hotel Facility

Thermographer:
Building Diagnostics Group

Equipment Room F



Object Parameters

IR information	Value
File name	lr_0310.jpg
Camera serial number	25300633
Camera lens	45
IR Text Comment	Value
Location	Equipment Room F
Sub location	Panel AD-5
Fault	B
Label	Value
IR : max	162.5°F
SP01	162.1°F
SP02	108.3°F

Potential Problem

Action Code Correct prior to next maintenance period.
B

Action Taken

Date:

Initials:

This report reflects apparent conditions at the time of the survey and does not include all hazards not described nor indicate that other hazards do not exist. BDG, Inc does not make any warranty concerning the activities described in this report, nor shall we be liable in any manner for personal injury or property damage or loss of any kind arising from connected with this survey, including failure to report.